PHUONGHONG SHIP REPAIR AND MARINE SERVICE CO., LTD

Address: 289 Le Van Sy street – Tan Binh District - Ho Chi Minh City Mobile / WhatsApp/ WeChat: +84 793331062

Email: info@phuonghongmarine.com http://phuonghongmarine.com









WORKLIST REPORT

To:	Amoysailing Maritime Co., Ltd	From: SHIP REPAIR AND MARINE SERVICE CO.,Ltd Date: 22 .MAR. 2022		
Att:	26H, No.99,Lujiang Avenue,Xiamen 361001, China			
Email:	management@amoysailing.com	Tel/Fax: +84 93331062		
SHIP NAME: AMOY PROGRESS		Our Ref. No: PHB-22301/2022.		

ITEM: REPAIR AND SUPPLY SPARE PART AIR CONDITION at VUNG TAU - VIET NAM

Description	Unit	Q.ty	Code	Remarks
Air conditioning evaporator 1150 x 1100x250mm copper pipe Ø 10	Job	1.0		
Workers to completely disassemble and install the indoor unit	Job	1.0		
Stop Valve 1-1/8" Hongsen	Set	2.0		
Solenoid vlalve7/8" Danfoss	Set	2.0		
OTHER SERVICE				
PCR Test Covid -19 for the job	Person	4.0		
Transportations, custom clearance, port entre fee, boarding fee, immigration formalities, port formalities, all Working/travelling hours, etc	Job	1.0		z.
	Air conditioning evaporator 1150 x 1100x250mm copper pipe Ø 10 Workers to completely disassemble and install the indoor unit Stop Valve 1-1/8" Hongsen Solenoid vlalve7/8" Danfoss OTHER SERVICE PCR Test Covid -19 for the job Transportations, custom clearance, port entre fee, boarding fee, immigration formalities, port formalities, all Working/	Air conditioning evaporator 1150 x 1100x250mm copper pipe Ø 10 Workers to completely disassemble and install the indoor unit Stop Valve 1-1/8" Hongsen Set Solenoid vlalve7/8" Danfoss OTHER SERVICE PCR Test Covid -19 for the job Transportations, custom clearance, port entre fee, boarding fee, immigration formalities, port formalities, all Working/ Job	Air conditioning evaporator 1150 x 1100x250mm copper pipe Ø 10 Workers to completely disassemble and install the indoor unit Stop Valve 1-1/8" Hongsen Set 2.0 Solenoid vlalve7/8" Danfoss Set 2.0 OTHER SERVICE PCR Test Covid -19 for the job Transportations, custom clearance, port entre fee, boarding fee, immigration formalities, port formalities, all Working/ Job 1.0	Air conditioning evaporator 1150 x 1100x250mm copper pipe Ø 10 Workers to completely disassemble and install the indoor unit Stop Valve 1-1/8" Hongsen Set 2.0 Solenoid vlalve7/8" Danfoss Set 2.0 OTHER SERVICE PCR Test Covid -19 for the job Transportations, custom clearance, port entre fee, boarding fee, immigration formalities, port formalities, all Working/ Job 1.0

Conclusion: The Job for REPAIR AND SUPPLY SPARE PART AIR CONDITION as ,mentioned above have been checked / tested and confirmed by Chief Engine

MASTER MV AMOY PROGRESS

SHIP REPAIR AND MARINE SERVICE CO., LTD





TECHNICAL DEPT. MR NHAN